1st final bill

M. A. R. 57 (Rule 116) No. D

Measurement Book

225637

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

Name of work :- Desilting of drains & removal of debris & providing covering Slab for dasarahalli ward No-15.

Estimate Cost :- RS 20.00 lakhs.

Jof Code :- 015-20-000115, P-Code :- 1771

N.O No :- EE|DD|N.O|123|2020-21, Dt:05-11-2020.

AA No :- EE|DD|AS|87|2020-21, Dt: 03-07-2020

TS No :- EE|DD|TS|19|2020-21, Dt: 03-07-2020.

Tender Notification No :- BBMP|EE|DD|Tender|12|2020-21, Dt: 28-07-2020

Agency :- Sri Muniraj Naik

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇ.
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಜಿ.ಜಿ.ಎಂ.ಪಿ.

Scanned by CamScanner

Abstract

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions					Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
Sl No	Description of work	unit	Qty		Rate		amount
2.	Removing & refixing Stone Slabs.	Sqm	3598.00		97.00		349025.00
1.	Earthwork excavation by manual in Ordinary Soil	Cum	1439.01		182.00		261900.00
3.	Providing & fixing Precast RCC Slab 100 mm thick	Sqm	622.50		1421.00		884573.00
					Sub total	=	1495498.00
					GST 12%	=	179460.00
					Grand total	=	1674958.00

(Sixteen lakhs Seventy four thousand Nine hundred & fifty eight Rupees)

30/12/20
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು 560073

Audited and admitted for Rs. 1674958-00
Passed by Cheque for Rs. 1579688-00
(Fifteen Lakh Nineteen thousand Six Hundred Eighty Eight only)
Serial No. 155270 - ಎ

M. A. R. 57 (Rule 116) No. D 225638

Measurement Book

Name of work .....
From ..... To .....
Name of Contractor of nature of Agency .....
Date of commencement of work ..... Exe. Engineer

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

Certificate :-

1. The work spot has been inspected & the work is found to be ne
2. The Contractor has done work satisfactorily.
3. The Contractor cleared all debris from the work spot.

30/12/20

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು 560073

Scanned by CamScanner